Service Information Bulletin

FAULT PATTERN CATALOG: VIBRATION WHEN BRAKING/STEERING WHEEL VIBRATION

B34 07 18 [SI] December 2021

This Service Information Bulletin replaces TRI 34 07 18 dated July 2021.

This bulletin is information only, no claim information intended.

What's New (Specific text highlighted):

• Conversion of TRI to SI B

udesignates changes to this revision

▼ Complaint

INFORMATION

The attached fault pattern catalog is designed to help improve the diagnosis of "Steering wheel vibrations when braking". It will also ensure audit-proof and authorized billing of brake discs, brake pads and peripheral parts in accordance with the applicable warranty guidelines.

For other causes, follow the warranty billing guidelines.

ATTACHMENT

B34 07 18 Defect catalog

Measure

MODEL

F06 (M6 Gran Coupe)	F10 (M5 Sedan)	F12 (M6 Convertible)	F13 (M6 Coupe)
F80 (M3)	F82 (M4 Coupe)	F83 (M4 Convertible)	F85 (X5M)
F86 (X6M)	F87 (M2 Coupe)	F90 (M5 Sedan)	F91 (M8 Convertible)
F92 (M8 Coupe)	F93 (M8 Gran Coupe)	F95 (X5 M Sports Activity Vehicle)	F96 (X6 M Sports Activity Coupe)
F97 (X3 M Sports Activity Vehicle)	F98 (X4 M Sports Activity Coupe)	G80 (M3 Sedan)	G82 (M4 Coupe)
G83 (M4 Convertible)	Produced from 9/1/11 with standard compound brake disc		

Validity information

Service Information Bulletin Metadata

Model series: F87, G80, G82, G83, F80, F82, F83, F06, F12, F13, F92, F96, F91, F10, F93, F90, F95, F85, F86, F97, F98 Engine range: N55, S55, S58T, S58O, S63T, S63M, S63R Body style: COUPE, LIM, CABRIO, SC, GEFZG Fault codes:

Repair overviews

Attachments

B34 07 18 Defect Catalog.PDF